


EXIT 16

Diamondhead, MS



Beginning Monday, August 25, 2014 between 3:30 p.m. and 5:30 p.m. (Monday - Friday) traffic entering Diamondhead via the Eastbound Exit Ramp will be re-routed. Traffic will exit to the South and proceed on Yacht Club Drive through the roundabout and thence travel back northward to Diamondhead Drive. MDOT has recommended this change to traffic flow as a short-term solution until a viable permanent solution can be made to alleviate traffic congestion on the off-ramp and I-10 Eastbound lanes.